

OFFICIAL SAFETY NOTICE

GOSSAMER PRO AGX+ [CK 6037]

Full Speed Ahead (FSA) is declaring an official voluntary Recall statement about GossamerAGX+ crankset which had been delivered between January 2022 - December 2022.

FSA has received reports of crank arms becoming loose or "wobbly" and detaching from the crank/spindle interface that is held together by a press-fit interference and bonding agent. Only the drive-side crank arm is susceptible to bonding failure. At first signs of failure the rider may find that crank arm becoming loose or "wobbly" while riding. They should stop usage as continued riding could pose a risk of instability while riding or the crank arm becoming detached creating a fall hazard which could result in minor injuries.



COMPLIANCE TESTING

Prior to receiving reports, the crankset passed all international ISO testing standards.

INSPECTION OF CRANKSET

Inspect Gossamer AGX+ [CK-6037] cranksets and bicycles pre-assembled by OEM with Gossamer AGX+ CK-6037 cranksets that may be within the serial number range stated below. FSA will be requesting all cranksets within serial number ranges starting with B1, B2 and B3 to be returned to FSA for replacement. The serial number range is shown highlighted below.





> ACTION PLAN

FSA is preparing to replace cranksets for all below listed stakeholders (such as consumers, dealers, distributors, and bicycle manufacturers - referred to as OEM) with the new Gossamer Pro AGX+ CK-6037 cranksets.

> CONSUMERS

Consumers self-inspect own bicycle and in case of potential technical issues refer to the preferred bike dealer.

Dealers will be instructed to inspect their inventory and customers' cranksets verifying if they are within the specified range. If so, a crankset complying with new specification will be shipped free of charge.

> DEALERS (Bike Shops)

Dealers who purchase FSA crankset from distributors or as original equipment pre-assembled on bicycles (OEM) will be contacted by the bike Distributor and OEM via telephone or email.

Dealers will be instructed to inspect their inventory of Gossamer Pro AGX+ CK-6037 cranksets (or inventory of bicycles with Gossamer Pro AGX+ CK-6037 cranksets) and consumer bicycles with Gossamer Pro AGX+ CK-6037 cranksets that fall within the serial number range beginning with B1-B2-B3.

Dealers that receive claims and service support requests from end users can refer to FSA's regional official service center for any question or support based on below list.

In case the crankset faced above mechanical issue, Dealers would be able to order a new crankset referring to the official FSA regional distributor.

> <u>DISTRIBUTORS - BICYCLE MANUFACTURER</u> (OEM)

Distributors and Bicycle Manufacturers (OEM) who sold Gossamer Pro AGX+ and/or pre-assembled Gossamer Pro AGX+ CK-6037 cranksets on their bicycles have been contacted by FSA to stop shipment cranksets inventory and bicycles built with Gossamer Pro AGX+ CK-6037.

Inspection of Distributors and OEM's inventory has begun for cranksets that are within the prospective range. Any crankset within the prospective range will be replaced free of charge.

Distributors and OEM are free to contact their dealers who have purchased Gossamer AGX+ CK-6037 cranksets or bicycles with Gossamer AGX+ CK-6037 cranksets installed requesting Dealers inspect their inventory and any cranksets purchased by Consumers.

Dealers will be able to contact below listed official FSA regional service centers about replacement procedure, reimbursement, or any of other related information.

FSA will be requesting all cranksets within serial number ranges with **B1**, **B2** and **B3** to be returned. Shipping costs associated to return the cranksets will be covered.



SUITABLE SOLUTION

The following models (CK-6138 / CK-6038 / CK-6027) are suitable replacement solutions to the issued CK-6037 MEGAEXO AGX+.



OFFICIAL SERVICE CENTER (contact)

Customers can contact FSA official Service Center to receive further information or service.





NORTH AMERICA			
COUNTRY	E-MAIL	TEL	
USA	Info@bti-usa.com	1 800 558 8324	
USA	customerservice@qbp.com	1 952 941 9391	
USA	info-us@hlc.bike	1 888 522 2453	
USA	Info@jbimporters.com	1 800 666 5000	
USA	sales@osco.bike	1 414 461 8380	
USA	Info@khsbicycles.com	1 310 632 7173	
CANADA	Info@orangesportsupply.com	1 877 990 5554	
CANADA	Info@cycleslambert.com	1 888 522 2453	
INTERNATIONAL	recall-USA@fullspeedahead.com	877-743-3372	

SOUTH AMERICA		
COUNTRY	E-MAIL	TEL
BRASIL	alancesar@daxbike.com	+55.86.3131.7600
BRASIL	sac@cervelobr.com	+11 9 9337 5434
CHILE	info@interbikes.cl	+56.9 3436 0304
COLOMBIA	comercial@grafamsports.com	+57.310.839.6660
COSTA RICA	rigobertozuniga@elsprinter.com	506.2241.4818
ECUADOR	info@baseextreme.com.ec	+593.7.281.4686
EL SALVADOR	info@probikesv.com	502.521.6360
GUATEMALA	Info@Probikes.Net	502.521.6360
JAMAICA	cyclecity_fitnesscentre@yahoo.com	876.754.7433
MEXICO	contactanos@grupomercurio.mx	800 2288 242
PANAMA	desarrollodeportivo40@gmail.com	+507 6050-4513
PANAMA	natachagrau@rufuslatinamerica.com	+584.14.896.4644
TRINIDAD	larry.ali@motorcycleetc.com	868-693-2754
VENEZUELA	contactanos@subicicleta.com	+58 4143312912
INTERNATIONAL	recall-USA@fullspeedahead.com	877-743-3372

EUROPE		
COUNTRY	E-MAIL	TEL
BENELUX	Info@codagex.be	0032 14347474
BULGARIA	Aftermarket@sprintmaxcom.com	00359 32600897
CZECH REP.	Sport@dema.sk	00421 346945111
CZECH REP.	info@zookee.cz	+420 461 530 983
CYPRUS	Mariap@andreou.com	00357 – 24811031
DENMARK	Service@konggaard.dk	+45 8722 3306
DENMARK	Info@bikersbest.dk	0045 63168001
ESTONIA	info@veloplus.ee	00372 5070860



FINLAND	Info@bikersbest.dk	0045 63168001
FINLAND	info@onesport.fi	+3458 207691970
FRANCE	Info@esm-sport.com	0033 0479843680
FRANCE	Info@savoye.fr	00334 74 36 13 77
FRANCE	fsa@comet.es	0034-943331393
		0049 07159 9459-
GERMANY	fsagermany@fullspeedahead.com	30
GREECE	info@bikeformance.gr	0030 2182189414
HUNGARY	velossimo.hu@gmail.com	0036 302212929
ITALY	Info@rms.it	0362 27301
ITALY	Info@ciclopromo.com	0039-04231996363
MALTA	Magricyc@nextgen.net.mt	00356-21414399
NORWAY	Service@konggaard.dk	+45 8722 3306
NORWAY	Info@bikersbest.dk	0045 63168001
POLAND	Sport@dema.sk	00421-346945111
POLAND	filip.s@porebarowery.pl	+ 48 12 264 90 24
PORTUGAL	Geral@ciclocoimbroes.com	00351 - 223794461
ROMANIA	Office@crossbike.ro	0735 151 260
SLOVAKIA	Sport@dema.sk	00421-346945111
RUSSIA	sergey@velomarket-cska.ru	007-4956132938
SLOVENIA	Veb-company@siol.net	0038-614303922
SOUTH AFRICA	fsa@capegrosports.co.za	0027 72 3799074
SPAIN	fsa@comet.es	0034-943331393
SPAIN	Alfonso@bhsa.es	0034-945135202
SWEDEN	info@boove.se	0046 8 761 0266
SWISS	Daniele@belimport.ch	0041 91 260 35 15
		0090 236 213 00
TURKEY	aftermarket@accellbisiklet.com.tr	45
UKRAINE	shop@veloplaneta.com.ua	380-991002909
U.K. & IRELAND	fsa.uk@fullspeedahead.com	0044-2392521912
INTERNATIONAL	recall-europe@fullspeedahead.com	(39) 039 6885265

ASIA PACIFIC		
COUNTRY	E-MAIL	TEL
TAIWAN	support@fullspeedahead.com.tw	(+)886 4 2331 9134
AUSTRALIA	sales@advancetraders.com.au	+61 (0) 7 38618900
AUSTRALIA	info@mchimports.com	1300 783 556
CHINA	daniel@fullspeedahead.com.cn	+86 512 5702 2458
HONG KONG	info@locationcycles.com	+852 24418628
	customerservice@bab-	
INDONESIA	indonesia.com	+62 21 30052621
IRAN	info@orchid.ir	+98 55390303 21
ISRAEL	tzahi@dzsystems.co.il	+97 289188983



JAPAN	Zac_r@e-ftb.co.jp	+81-52 5048345
JAPAN	fsa_vision@podium.co.jp	+81 742643555
MALAYSIA	yeann@senaik.com	+60 3 3358 6650
MALAYSIA	info@slmbicycle.com	+6012 4253369
NEW ZEALAND	sales@wideopen.co.nz	+64 7 3453280
PHILIPPINES	inquiry@nanotechtradinginc.com	+63 32 2558853
SINGAPORE	trilabsg@gmail.com	+65 96254225
SINGAPORE	chris@yapbicycle.co	+65 91113130
SINGAPORE	info@czinc.cc	+65 8714 1322
SOUTH KOREA	daniel@watts-sports.com	+82 02 7978279
VIETNAM	info@bikelife.com.vn	+84 8 54124217
UAE	info@rcdxb.com	+971 4 3697441
UAE	contact@beyondthebeach.com	+971 4 289 4858
THAILAND	saknanon.wat@peloton.co.th	02-095-3560
INTERNATIONAL	recall-asia@fullspeedahead.com	+886 4 23331 9134

FURTHER INFORMATION

More information could be found in the dedicated page on the FSA website: https://www.fullspeedahead.com/it/support/recall.

SHOP LOCATOR

International Shop Locator: https://www.fullspeedahead.com/it/find-store

Q&A

Q. WHY IS FULL SPEED AHEAD CONDUCTING THIS RECALL?

A. We are conducting this recall to keep our customer's safe and prevent possible injuries by removing the product from the marketplace.

Q. HOW CAN I TELL IF MY CRANKSET IS AFFECTED BY THE RECALL?

A. Gossamer Pro AGX+ CK-6037 drive crank arms that are within the serial numbers beginning B1, B2, B3 are affected by this recall. Serial numbers are located on the backside of the drive side crankarm by pedal threads.

Q. HOW CAN I TAKE ADVANTAGE OF THE RECALL?

A. Take your bicycle to your local bicycle dealer for inspection and replacement. Dealers can contact us at our toll-free phone number 877-743-3372 or email Recall-USA@fullspeedahead.com to complete the recall.



Q. WHAT IS THE PROBLEM WITH MY [PRODUCT]?

A. Full Speed Ahead (FSA) has received reports of crank arms becoming loose or "wobbly" and detaching from the crank/spindle interface, posing fall and injury hazards. Only the drive-side crank arm is susceptible to bonding failure.

Q. I NO LONGER HAVE THE RECEIPT FOR THE PRODUCT. CAN I STILL RETURN IT?

A. Yes. A replacement crankset and repair will be provided at no charge.

Q. WILL I RECEIVE A REFUND FOR THE PRODUCT?

A. No. Customers whose cranksets are in the affected serial number range will be provided with a free replacement crankset from Full Speed Ahead that your local bicycle dealer will professionally install.

Q. WILL I BE ABLE TO REPAIR THE PRODUCT MYSELF?

A. No. Please visit your local bicycle dealer for a free replacement and repair.

Q. CAN I REPAIR THE PRODUCT MYSELF?

A. No. We urge you not to attempt to repair the product yourself. Please visit your local bicycle dealer for a free replacement and repair.